Laboratory Report Adhesion

Date: 27.10.2008 Project #: WN30733/08
Test costs: CHF 750.-

Project name: Adhesion test

Location: -

Customer: Pilkington Plyglass, England

Date samples received: 23.09.2008

Description of samples received and adhesion testing:

(according to CQP 033-1, CQP 034-1 and CQP 555-1; CQP = Sika Corporate Quality Procedure)

		1 st Pretreatment	2 nd Pretreatment	3 rd Pretreatment	Sealant /	Results:
No	Sample:	Step:	Step:	Step:	Adhesive:	
1.	Glass coated Graphite BS 18B25	Sika®	-	-	Sikasil®	1
		Cleaner P			SG-500	1 ; -
2.		Sika®	-	-	Sikasil®	4
		Cleaner-205			SG-500	' -
		Sika®	-	-	Sikasil®	4
		Cleaner P			IG-25	11-
4.		Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25	' -
5.		Sika®	-	-	Sikasil®	
		Cleaner P			IG-25 HM	' -
6.		Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25 HM	1 -

Additional Remarks:

The adhesion of Sikasil® SG-500, IG-25 and IG-25 HM to the submitted samples was excellent under aforementioned conditions.

>75% cohesive failure >25% cohesive failure <25% cohesive failure 0% cohesive failure Paint/substrate rupture Primer failure BK Bubbles in adhesive B T Bubbles on substrate surface Tunneling K FH Uncured adhesive on surface Film adhesion Foam structure on surface Separation on the edges

>95% cohesive failure

Approved by:

u. lille

(Ulli Müller, Product Engineer) Market Field Façade, Fenestration & Insulating Glass

4.21

(Felix Fischer)
Market Field Façade, Fenestration & Insulating Glass

Important note:

The information contained herein and any other advice are given in good faith based on Sika's current knowledge and experience of the products when properly stored, handled and applied under normal conditions in accordance with Sika's recommendations. The information only applies to the application(s) and product(s) expressly referred to herein. In case of changes in the parameters of the application, such as changes in substrates etc., or in case of a different application, consult Sika's Technical Service prior to using Sika products. The information contained herein is only provided with the purpose of providing the user with additional information as to Sika's products. It does not relieve the user of the products from testing them for the intended application and purpose. All orders are accepted subject to our current terms of sale and delivery. Users should always refer to the most recent issue of the local Product Data Sheet for the product concerned, copies of which will be supplied on request.



Page 1 of 3 08_30733Wn.doc

Laboratory Report Adhesion

Date: 27.10.2008 Project #: WN30733/08
Test costs: CHF 750.-

Project name: Adhesion test

Location: -

Customer: Pilkington Plyglass, England

Date samples received: 23.09.2008

Description of samples received and adhesion testing:

(according to CQP 033-1, CQP 034-1 and CQP 555-1; CQP = Sika Corporate Quality Procedure)

		1 st Pretreatment	2 nd Pretreatment	3 rd Pretreatment	Sealant /	Results:
No	Sample:	Step:	Step:	Step:	Adhesive:	
1.		Sika®	-	-	Sikasil®	4
		Cleaner P			SG-500	1 -
2.		Sika®	-	-	Sikasil®	4
		Cleaner-205			SG-500	1 :-
3.	Glass coated	Sika®	-	-	Sikasil®	4
		Cleaner P			IG-25	1 :-
4.	Harmony Bronze BS 08B27	Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25	1 -
5.		Sika®	-	-	Sikasil®	4
		Cleaner P			IG-25 HM	1 1 -
6.		Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25 HM	1 -

Additional Remarks:

The adhesion of Sikasil® SG-500, IG-25 and IG-25 HM to the submitted samples was excellent under aforementioned conditions.

>75% cohesive failure >25% cohesive failure <25% cohesive failure 0% cohesive failure Paint/substrate rupture Primer failure BK Bubbles in adhesive B T Bubbles on substrate surface Tunneling K FH Uncured adhesive on surface Film adhesion Foam structure on surface Separation on the edges

>95% cohesive failure

Approved by:

v. lille

(Ulli Müller, Product Engineer)
Market Field Façade, Fenestration & Insulating Glass

4.21

(Felix Fischer)
Market Field Façade, Fenestration & Insulating Glass

Important note:

The information contained herein and any other advice are given in good faith based on Sika's current knowledge and experience of the products when properly stored, handled and applied under normal conditions in accordance with Sika's recommendations. The information only applies to the application(s) and product(s) expressly referred to herein. In case of changes in the parameters of the application, such as changes in substrates etc., or in case of a different application, consult Sika's Technical Service prior to using Sika products. The information contained herein is only provided with the purpose of providing the user with additional information as to Sika's products. It does not relieve the user of the products from testing them for the intended application and purpose. All orders are accepted subject to our current terms of sale and delivery. Users should always refer to the most recent issue of the local Product Data Sheet for the product concerned, copies of which will be supplied on request.

Sika®

Page 2 of 3 08_30733Wn.doc

Laboratory Report Adhesion

Date: 27.10.2008 Project #: WN30733/08
Test costs: CHF 750.-

Project name: Adhesion test

Location: -

Customer: Pilkington Plyglass, England

Date samples received: 23.09.2008

Description of samples received and adhesion testing:

(according to CQP 033-1, CQP 034-1 and CQP 555-1; CQP = Sika Corporate Quality Procedure)

		1 st Pretreatment	2 nd Pretreatment	3 rd Pretreatment	Sealant /	Results:
No	Sample:	Step:	Step:	Step:	Adhesive:	
1.	Glass coated, red	Sika®	-	-	Sikasil®	1
		Cleaner P			SG-500	1 -
2.		Sika®	-	-	Sikasil®	4
		Cleaner-205			SG-500	-
3.		Sika®	-	-	Sikasil®	1
		Cleaner P			IG-25	1 -
4.		Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25	' -
5.		Sika®	-	-	Sikasil®	1
		Cleaner P			IG-25 HM	' -
6.		Sika®	-	-	Sikasil®	4
		Cleaner-205			IG-25 HM	1 -

Additional Remarks:

The adhesion of Sikasil® SG-500, IG-25 and IG-25 HM to the submitted samples was excellent under aforementioned conditions.

>95% cohesive failure >75% cohesive failure >25% cohesive failure <25% cohesive failure 0% cohesive failure Paint/substrate rupture Primer failure BK Bubbles in adhesive B T Bubbles on substrate surface Tunneling K FH Uncured adhesive on surface Film adhesion Foam structure on surface

Separation on the edges

Approved by:

u. lille

(Ulli Müller, Product Engineer) Market Field Façade, Fenestration & Insulating Glass

4.21

(Felix Fischer)
Market Field Façade, Fenestration & Insulating Glass

Important note:

The information contained herein and any other advice are given in good faith based on Sika's current knowledge and experience of the products when properly stored, handled and applied under normal conditions in accordance with Sika's recommendations. The information only applies to the application(s) and product(s) expressly referred to herein. In case of changes in the parameters of the application, such as changes in substrates etc., or in case of a different application, consult Sika's Technical Service prior to using Sika products. The information contained herein is only provided with the purpose of providing the user with additional information as to Sika's products. It does not relieve the user of the products from testing them for the intended application and purpose. All orders are accepted subject to our current terms of sale and delivery. Users should always refer to the most recent issue of the local Product Data Sheet for the product concerned, copies of which will be supplied on request.



Page 3 of 3 08_30733Wn.doc